



D0 Status Report 10/24/2005

Taka Yasuda Fermilab



Data Taking for 10/17 - 10/23



Day	Delivered	Recorded	Eff.	Comments
10/17 (Mon)	2.55 pb ⁻¹	2.43 pb ⁻¹	88 %	1 hour downtime due to MDT crates in a bad state after a large halo spike.
10/18 (Tue)	2.06 pb ⁻¹	1.89 pb ⁻¹	92 %	
10/19 (Wed)	0.59 pb ⁻¹	0.55 pb ⁻¹	94 %	
10/20 (Thu)	2.09 pb ⁻¹	1.69 pb ⁻¹	81 %	Surpassed 1 fb ⁻¹ on tape. LCW problem caused Solenoid to slow dump, then fast dump and quench. Luminosity reported by VME electronics.
10/21 (Fri)	2.90 pb ⁻¹	2.70 pb ⁻¹	93 %	During squeeze of store 4462, received 108 rad/min.
10/22 (Sat)	3.58 pb ⁻¹	3.34 pb ⁻¹	94 %	Controlled access to replace a Calo daughter card. During squeeze of store 4464, received 170 rad/min.
10/23 (Sun)	3.17 pb ⁻¹	2.92 pb ⁻¹	92 %	During squeeze of store 4465, received 94 rad/min.

	_	_		
10/17-10/23	16.94 pb ⁻	15.52 pb ⁻¹	92 %	
- , - , -				



Notable Events




- 10/17 (Mon)
 - 1 hour downtime due to MDT crates being in a bad state after a large halo spike.
- 10/20 (Thu)
 - D0 recorded luminosity surpassed 1000 pb⁻¹.
 - Solenoid tripped due to LCW high conductivity.
 - A repaired LCW pump was brought on-line, contaminating the low conductivity of the water.
 - This triggered a slow dump. Shortly into the slow dump, we went into a fast dump due to an overly tight quench protection limit.
 - Overall downtime of 3.5 hours.
 - Switched to the luminosity reporting by the VME electronics system from the one by the NIM electronics.





Run II Integrated Luminosity

19 April 2002 - 20 October 2005








Daily Data Taking Efficiency


19 April 2002 - 20 October 2005





Oct. 6 Ramp down - Chimney "B" voltage Just made it below the quench detection limit








Luminosity reporting by new VME electronics





New electronics:

- Less sensitive to backgrounds and deadtime.
- Less prone to saturation effects.



Accesses



- 10/17 (Mon)
 - Install and test a Run IIb muon PDT Control Board.
- 10/18 (Tue)
 - Investigate FPS DFE low voltage problems.
- 10/22 (Sat)
 - Replace a calorimeter daughter card and a pulser power supply.







1 fb-1 to Tape!

Please come celebrate at the User's Center At 5:15 Today